H	#	Hits	Search Text	DBs	Time Stamp	Comment s	Error Definition	E RO RA
L1		2	50	USPA	2003/09/1 6 08:16			0
1.2		3	(("6425027") or ("6356967") or ("5282112")).PN.	USPA T	2003/09/1 6 09:01			0
L3		3	(("5359714") or ("5359714") or ("5327570")).PN.	USPA T	2003/09/1 6 09:02			0
7. 4.		25	("0488057") or ("0237193") or ("0206580") or ("5308926") or ("5293636") or ("5293636") or ("5245320") or ("5243704") or ("5243704") or ("5207583") or ("5207583") or ("5122691") or ("5135785") or ("513538") or ("4975695") or ("4975695") or ("4971563") or ("4805091") or ("4805091") or ("4777615") or ("4670855") or ("4670855") or	USPA	2003/09/1 6 09:03			0
1.5		2	computer and (backplane same interconnector same slots)	USPA	2003/09/1 6 09:05			0

	Search Text		Hits	
USPA 2003/09/1 ots) T 6 09:12	nter and plane same sest same slo	computer and (backplane same bridge\$1 same slots)	computer and (backplane same bridge\$1 same slo	
EPO; JPO; DERW ENT; IBM TDB	iter and plane same je\$1 same slot	computer and (backplane same bridge\$1 same slots)	computer and 6 (backplane same bridge\$1 same slot	